CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS#	K-2664	
------	--------	--

	· 1550m.
1.	ADDRESS/LOCATION: 304 West Street, East Side, Harrington
2.	FUNCTION(S): historic Residence current Residence
3.	YEAR BUILT: 1860 CIRCA?: ARCHITECT/BUILDER:
4.	STYLE OR FLOOR PLAN:
5.	INTEGRITY: original site 🖂 moved 🗌
	if moved, from where other location's CRS # year
	list major alterations and additions with years (if known) a. See narrative description b.
6.	CURRENT CONDITION: excellent good fair poor
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
	 a. Overall shape: Rectangular core with long rear Stories: 2 addition Additions: 1
	b Structural system (if known): Frame
	c. Foundation: materials: Concrete basement: full 🛛 partial 🗌 not visible 🗌 no basement 🗌
	 d. Exterior walls (original if visible& any subsequent coverings): Original would have been clapboard; now sheathed with vinyl siding.
	e. Roof: shape: Side gable materials: Asphalt shingle cornice: Encapsulated with vinyl dormers: n/a chimney: location(s): One on rear addition; concrete block, exterior
8.	DESCRIPTION OF ELEVATIONS:
	a. Facade: Direction: W 1) Bays 2 2) Windows fenestration Irregular type 1/1 sash
	trim Vinyl

shutters

n/a

Facade (cont'd)

3) Door(s)

location Toward north end type Single-leaf, paneled

trim Wood

4) Porch(es) Replaced; added small front conrete porch with vinyl columns

b. Side: Direction: N

1) Bays 4

2) Windows

fenestration Irregular

type 1/1 double-hung sash

trim Aluminum shutters None

3) Door(s)

location n/a type n/a trim n/a

4) Porch(es) n/a

c. Side: Direction: S

1) Bays 4

2) Windows

fenestration Irregular

type 1/1 double-hung; and casement windows on rear addition

trim Vinyl shutters n/a

3) Door(s) 2

location Rear wing

type One single pedestrian door; glazed top half; one double glass door

trim Vinyl

4) Porch(es) Side, modern deck (wood) and enclosed side porch

d. Rear: Direction: E

1) Bays 1.5

2) Windows

fenestration Irregular

type 1/1 sash, paired on first floor and smaller casement window on 2nd floor

trim Vinyl shutters n/a
3) Door(s) n/a location n/a type n/a trim na/

4) Porch(es) n/a

9. INTERIOR: n/a

10. LANDSCAPING: Grassed yard

11. OTHER COMMENTS: n/a

CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# K-2664

1.	ADDRESS/LOCATION: 304 West Street, East Side, Harrington	
2.	FUNCTION(S): historic Storage shed (privy) current Storage shed	
3.	YEAR BUILT: 1920 CIRCA?: X ARCHITECT/BUILDER:	
4.	STYLE/FLOOR PLAN: Rectangular; vernacular	
5.	INTEGRITY: original site ⊠ moved ☐ if moved, from where original location's CRS #	<u>year</u>
	list major alterations and additions with years (if known) a. b.	year
6.	CURRENT CONDITION: excellent good fair	poor 🛚
7.	DESCRIPTION:	
	a. Structural system Frame; shed	
	b. Number of stories 1	
	c. Wall coverings Vertical wooden siding	
	d. Foundation None	
	e. Roof structural system Frame coverings Asphalt shingle openings n/a	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: S1) bays: 12) windows: 1 two-pane window	
	3) door(s): n/a	
	4) other: n/a	

CRS	#	K-2664
CK2	#	N-2004

	b.	Side: direction: W 1) bays: 1 2) windows: n/a
		3) door(s): n/a
		4) other: n/a
	C.	Side: direction: E 1) bays: 1 2) windows: n/a
		3) door(s): 1 pedestrian door; opening only; door missing
		4) other: n/a
	d.	Rear: direction: N
		1) bays: 1 2) windows: n/a
		3) door(s): n/a
		4) other: n/a
9.	INTE	RIOR (if accessible):
	a) Flo	oor plan Open
	b) Pa	artition/walls None
	c) Fii	nishes N one
	d) Fu	ırnishings/machinery None

CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	K-2664	

1.	ADDRESS/LOCATION: _304 West Street, East Side, Harrington	
2.	FUNCTION(S): historic Possibly small barn or equipment current Garage shed	
3.	YEAR BUILT: 1920 CIRCA?: ARCHITECT/BUILDER:	
4.	STYLE/FLOOR PLAN: Open plan; rectangular/vernacular	
5.	INTEGRITY: original site ⊠ moved ☐ if moved, from where original location's CRS #	<u>year</u>
	list major alterations and additions with years (if known) a. b.	<u>year</u>
6.	CURRENT CONDITION: excellent good fair 🖂	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	
	c. Wall coverings Horizontal wooden boards	
	d. Foundation Rests on concrete blocks	
	e. Roof structural system Frame-end gable coverings Asphalt shingle openings n/a	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: S1) bays: 12) windows: n/a	
	3) door(s): 1 garage door with bay; overhead door	
	4) other: n/a	

CRS#	K-2664	
------	--------	--

	b.	Side: direction: E1) bays: 22) windows: 2; irregular, nearly square shape, wooden frame, panes m	nissing
		3) door(s): n/a	
		4) other: n/a	
	c.	Side: direction: W 1) bays: 2 2) windows: 2, irregular, nearly square shape, wooden frame, panes m	nissing
		3) door(s): n/a	
		4) other: n/a	
	d.	Rear: direction: N 1) bays: 2 2) windows: 1, irregular, nearly square shape, wooden frame, panes m	nissing
		3) door(s): 1 pedestrian, single-leaf, wood	
		4) other: n/a	
) <u>.</u>	INTEI	ERIOR (if accessible):	
	a) Flo	loor plan Open	
	h) Pa	artition/walls None	
	5,14	artifolis and a second	
	c) Fir	inishes None	
	d) Fu	urnishings/machinery None	




CULTURAL RESOURCE SURVEY MAP FORM

CRS#	K-2664	

1.	ADDRESS/LOCATION: 304 West Street, East Side, Harrington
2.	NOT FOR PUBLICATION reason:
3.	LOCATION MAP:
	Indicate position of resource in relation to geographical landmarks such as streams and crossroads.
	(attach section of USGS guad map with location marked or draw location map.)

INDICATE NORTH ON SKETCH



•	•	•	•						•			•		•																,		2			- 1	. 1	•	_						
												•					,													,	. •	<u> </u>				Ù	_	•		_	•	·		
												-								_						_	•	•	•		_	•	•			•	•	•		•	•	•		
]			_	_		_	_	•	•			•	•			•	•	•	•	•	•	•		
											C]			_	_			•]	•		•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•		•	•	•		
								_	_]	_	9	H	A	10	,	•	*	•	•	•	•	•	•	•	•	٠	•	•	•	•	•	•	•	•	•		•	•	•		
							_	•	_		,]	•	V	•	•	, •		•	1	•	•	•	•	•	•	•	•	•		•	•	•	•	•	•	•	•	,	•	•	•		
	_	_	_	_		_	•	Ī	•			1	•	•	•	•	•		•	1	•		•	•	٠	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•		
		_			•	•	•	•	•			• —		j		•	C)		7	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•		•	•	•		
_	•	•	•		•	•	•	•	•		,	•	•	•	•	•	•		•	•	•	•	•	•	٠	•	•	•	•	•	•	•	•	•	•	•	•	•		•	•	•		
•	•	•	•	•	•	٠,	ز.	Q	Ι.			•	•	•	•	•	•		•	•	٠		•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•		•	•	•		
•	•	•	•	•	•	• >	4		<u>`</u>		•	•	•	•	•	•	•		•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•		•	•	•		
•	•	•	•	•	•	•	ľ	•	1		•	•	•	•	•	•	•		•	•	•		•	•	•	•	•	•	•	•	•	•	•		•	•	•	•		•	•	•		
•	•	•	•	•	•	•	<u> </u>		_		•	•		٠,	· ¬	•	•	•	•	·	•		•	•	•	•	•	•	•	•	•	•	•		•	•	•	•		•	•	•		
•	•	•	•	•	•	•	•	•	•	Ţ			1	 		-		T	•	1-	•	_	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•		•	•	•		
•	•	•	•	•	•	•	•	•	•		•	•	•	٠	•	•	•	1	•	•	•		•	•	•	•	•		•		•	•	•		•	•	•	•		•	•	•		
•	•	•	•	•	•	•	•	•	4	1	•	•	•	-	•	•	•		•	•	•		٠t]•	•	•	•	•	•	,	•	•	•	•	•	•	•	•		•		•		
٠	•	•	•	•	•	•	•	•	•	٦	•	•	•	•	•	•	•	1	•	•	•		•[•	•	•	•	•	•		•	•	•	,		•	•	•		•				
•	•	•	•	•	•	•	•	•	•			•	•	-	•	•	•		•	•			-	-	•	•	•	•	•		•	•	•		•		•	-		-				
•	•	•	•	•	•	•	•	•	•	-	ı	•	•	-	•	•	•	1		•	•		$\cdot $			•			•		•									-				
•	•	•	•	•	•	•	•	•	•		•	•	•	-	•	•	•	1		•			$ \cdot $	•	•				•							-								
•	•	•	•	•	•	•	•	•	1	7		•	•	•	•	•		. }					*	.		•																		
•	•	•	•		•	•	•	•				•	•	ŀ	•		•	. (•			.			•			•											-				
•	•	•		•	•	•	•	•	•			•	•		H	Ø	lΒ	Ø	٠/	•			.	•						,										-				
•	•	•	•	•	•	•	•		1	7		•	•	-	•		بنند. 1			•		-	.∖	(•						,														
•	•	-	•	•	•	•			•	٦		•		ŀ	•	•					-		.																					
•	•	•	•	•	•		•	•	•	-		•—		1		-	 -,		Ţ	-	-		-			•																		
•	•	•	•	•	•	•		•	•			•	•				•	,					-	-																				
•	•	•	•		•		•	•				•			•								•†	٠.																				
	•				•				•	1		×	· •		-		;_		1	-	۲.		_				•													•				
•	•									١	r-		۱-	٠.		-		,		•	٠.						1			١														
		•															•										ļ																	
																		,				,					ļ										_					•		
	•										.							,									ٳ			Ì								•				•		
	•										. 1	•	١.														J										-			_	_	_		
•]		•				_			-	•	•		_	•	•		
]					•	•			•	•	•		• -	•	•		
_									_			٠												_			ل		-	,		•	•		_	•	•	•		•	•	•	_	
												•							•		_			_		-		_	•	,	-					*					-7	•	-	
•										١	\mathcal{N}	es	ķ	-	. :	نج	77	C	27	_					•		•	•	•	•	•	•	•	•		•	•	•		•	•	•		
													-		-	-	•		-	•	-		-	•	•	•	•	•	•	•	•	٠	•	•	•	•	•	•		•	•	•		

CULTURAL RESOURCE SURVEY SURVEY UPDATE FORM

CRS#	K-2664	
UK3#	17-2004	

	- Tritrache.		
1.	HISTORIC NAME/FUNCTION: Re	eese Smith Property, Residence	
2.	ADDRESS/LOCATION: 304 West	Street, East Side, Harrington	
3.	CURRENT CONDITION: excelle	nt □ good □ fair ⊠ poor	demolished
4.	INTEGRITY: Some alterations, included	uding vinyl siding and side porch enclosure.	
5.	SETTING INTEGRITY: Setting seen	ns to be similar to the original survey in 1979.	
6. I	FORMS ADDED (give number of form	ns completed for each):	
	#: Form:	List property types:	and the second s
	1 CRS 2 Main Building Form	Residence	
	2 CRS 3 Secondary Building	Form Garage; storage shed	
0 CRS 4 Archaeological S			
0 CRS 5 Structure (Building-Like) Form			
	0 CRS 6 Structure (Land Feat	ure) Form	
0 CRS 7 Object Form 0 CRS 8 Landscape Elements Form CRS 9 Map Form N/A			
	0 CRS 14 Potential District Fo		
7.	SURVEYOR INFORMATION:		
	Surveyor name:	Lauren Archibald	
	Principal Investigator name:	Lauren Archibald	
	Principal Investigator signature:	Lanu Orchibale	
	Organization:	A.D. Marble & Company	Date: 7/22/2005

crs-10

	9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)): a) Time period(s) Pre-European Contact Paleo-Indian Archaic Woodland I Woodland II	
	1600-1750∀ Contact Period (Native American) 1630-1730∀ Exploration and Frontier Settlement 1730-1770∀ Intensified and Durable Occupation 1770-1830∀ Early Industrialization 1830-1880∀ Industrialization and Early Urbanization 1880-1940∀ Urbanization and Early Suburbanization 1940-1960∀ Suburbanization and Early Ex-urbanization	
	b) Geographical zone Piedmont Upper Peninsula Lower Peninsula/Cypress Swamp Coastal Urban (City of Wilmington)	
	c) Historic period theme(s)	
-	Agriculture Forestry Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Religion Religion Community Organizations Occupational Organizations Major Families, Individuals and Events	

8. OTHER NOTES OR OBSERVATIONS:

CRS# K-2664

FIRM (Pty

CULTURAL RESOURCE SURVEY LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION HALL OF RECORDS DOVER, DELAWARE 19901 (302) 678-5314



FOR OFFICE USE SMEY

CRS # Jacker
Quad
SPO map # #1 Lack to
Hundred
DOCUMEN* 20 06/78/04/7

	STREET LOCATION: 304 West Street, Harrington Che
}.	OWNER'S NAME: TEL. *
	ADDRESS:
١.	TYPE OF LOCUS: a) structure b) district c) archaeological site
	d) other
5.	SURROUNDINGS OF LOCUS: (check more than one of necessary)
	a) fallow field b) cultivated field c) woodland _
	d) scattered buildings Turn e) densely built upf) other
Б.	THREATS TO LOCUS: (check more than one if necessary)
	a) none known b) zoning c) roads d) developers
	e) deterioration f) other
7.	REPRESENTATION ON OTHER SURVEYS
	TITLE:
	TITLE:
	TITIE
3.	YOUR NAME: Carioll Welch gr. 181.
	YOUR ADDRESS:

USE BLACK INK ONLY

B. SKETCH MAP 9. COMENIS: Consider the following: llease indicate position of locus in relation to geographical landmarks such as strong out relationship to setting b) associated traditions or stories reade. noteworthy reatures d) comparison with others in area FACES WEST FAIR CONDITION USE BLACK INK ONLY INDICATE NORTH ON SKETCH

Form CRS-1 FOR OFFICE USE ONLY CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM CRS # KILLA DELAWARE BUREAU OF ARCHAEOLOGY AND HISTORIC Doug 5P0 map # 10-11-6 PRESERVATION Hundred HALL OF RECORDS 26-66/78/19/14 DOVER, DELAWARE 19901 DOCUMENT (302) 678-5314 1. ADDRESS OF STRUCTURE: 304 West Street Harring to, le 2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE: a) Overall shape - rectanglish stories - 2 - a bays wings Frame b) Structural system c) Foundation - Brick - Consiste Block materials basement - Turns d) Exterior walls materials asbutes almyles color(s) . white shape: materiale Gables - lite Green Compa e) Roof cornice dormers chimney location(s) - 1 estimo -2 interior f) Windows type - 1 over 1 oach - atte eyehow . 2 in sait shutters -- Thema g) Door spacing - Front anter trim _ w h) Porches location(s) - Front materials - wood supports - person small to trim - white i' Interior details (if accessible)

USE BLACK INK ONLY

3. CONDITION: good	deteriorated	
remarks:	gygyngalan dawn o brithann a dheadh a e eagle ar ag malain an ag 17 m. e. a dhean a h-air a bhliadh à eart. e	
4. INTEGRITY: a) original site		
c) if moved, when and from	where	
d) list major alterations a	nd dates (if known)	
5. DATE OF INITIAL CONSTRUCTION:		
ARCHITECT/BUILDER:		
7. RELATED OUTBUILDINGS:		
a) barnb) carriage house	c) garage d) privy	
) shop h) gardens	
•	k) other	
	- I smill aled	
B. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUE ASSOCIATIONS WITH HISTORIC EVENTS OR PER		
9. Primary References: (include location of	of reference).	
10. Surveyor: <u>Lavell Welch</u>		

K-2664

The property at 304 West Street includes a two-story dwelling (ca. 1860), a storage shed (ca. 1920), and a garage that dates to ca. 1920. The buildings occupy a grassy lawn which is landscaped with some trees. Currently, the property is in fair condition and is used for residential purposes. The parcel is surrounded by residential land use.

Dwelling. The two-bay, two-story, side-gable frame dwelling (ca. 1860) with a rear two-story addition faces west toward West Street. The walls of the dwelling are clad in vinyl siding that imitates German lap. Asphalt shingles cover the roof and the cornice line is encased in vinyl. The dwelling rests on a concrete foundation. The side entrance at the façade is covered by a metal door and is sheltered by a late-twentieth-century portico which is supported by vinyl columns that rest on a concrete foundation. Steps lead up from the sidewalk level to the entrance door. Similar to the fenestration of the rest of the dwelling, the windows at the west elevation are vinyl sash. Generally, the window openings are irregularly-placed, double-hung sash, although casement windows are present in the rear addition.

The rear two-story addition is side gable in orientation, facing south. A one-story hip roof porch addition runs along the south elevation and is accessed by a treated lumber deck. An exterior concrete block chimney flue is attached to the east elevation of the rear addition.

Storage Shed. A one-story frame storage shed (ca. 1920) whose walls are clad in vertical board siding is located northeast of the dwelling. The shed has a door opening at the east elevation and a window opening at the south elevation. The roof is heavily deteriorated and is caving into the walls of the structure.

Garage. Immediately east of the dwelling and southeast of the storage shed is a one-story, side-gable frame garage (ca. 1920) which is currently used for storage purposes. The walls of the garage are clad in horizontal wooden siding and rest on a concrete foundation. The roof is clad in asphalt shingles. A pedestrian door and window opening are located at the north elevation, while two two-light fixed sash windows provide light into each of the east and west elevations. An overhead garage door is located at the south, side gable elevation.

Historical Background. Deed transactions for the property located at 304 West Street, in Harrington, Delaware, could be definitively traced only to the year 1916. At an unknown date, Benjamin Harrington, an heir of Nimford Harrington, sold the property containing 11,250.0 square feet to Evan C. Reese for an unknown amount. On October 25, 1916, Evan C. and Sallie P. Reese conveyed the property containing 11,250.0 square feet along with "...all singular buildings, improvements, and fixtures" to Lillie E. Reese (Kent County Deed Books [KCDB] H20:477). On August 20, 1985, Lillie Reese Smith passed away and conveyed the property to her son, Ralph Clifton Smith. On December 12, 1986, Ralph Clifton Smith sold the property containing 11,250.0 square feet along "...with the improvements thereon erected" to Tracey Lou, LTD, a Delaware Corporation, for

\$22,000 (KCDB W42:262). On June 1, 1992, Tracey Lou, LTD lost the property in a lawsuit to the Wilmington Trust Company for the debt owed of \$12,451.25. On October 8, 1992, Carl M. Wright, the Sheriff of Kent County, sold the property containing 11,250.0 square feet along with "...improvements thereon erected" to Robert Hassett Jr., and his wife Hsiang-Hua, for \$7,700 (KCDB D52:124).

Bibliography

Kent County Deed Books (KCDB), Kent County Courthouse, Dover, Delaware.